



ELECTRICAL INSTALLATION CONDITION REPORT

REPORT No: EICR-20250718113500

This report documents an accurate assessment of the condition of the electrical installation and whether it is fit for continued service in accordance with BS7671:2018+A3:2024 (18th Edition)

20 Doninni Place
Gilesgate
Durham
DH1 1ES

The following work was carried out at the address above

Safety assessment requested by the client.

And was deemed to be:

SATISFACTORY

Company issuing this Report

Elvet Electrics
21 Monks Crescent
Durham
Durham
DH1 1HD
elvetelectrics@gmail.com
CPS Enrolment No: 50438

Issued on

18/07/2025

Inspected by

Steven Jennings

Reviewed by

Steven Jennings

Recommended re-test

18/07/2030

Report generated by electraform® certification software 2025 | www.electraform.co.uk